

### **GOVERNMENT OF KARANATAKA**



## Karnataka State Fire and Emergency Service District Fire Office, Fire Station Gadag-582101,

Email.ID- dfogadag@gmail.com

CR:37:Adv:DFO:Gadag:2025.

Date:25-06-2025

### Fire Safety Recommendation/Advice Certificate

Sub: Issue of 'Fire safety recommendation/Advice' to Bharatiya Education

Society ® Gadag Bipin Chikkatti School, Near Adavisomapur,

Mundaragi Road, Gadag. Tq & Dt: Gadag.

Ref: 1) Applicant Request Letter Dated: 23-06-2025

2) No.GBC(2)044/2020-21 dated 21-06-2022.

\_\*\_\*\_\*\_\*\_\*\_

With reference to the above cited subject, the premises of Bharatiya Education Society ® Gadag **Bipin Chikkatti School**, Ground Floor + Two Upper Floor only situated at Near Adavisomapur, Mundaragi Road, Gadag Tq & Dt: Gadag. Was inspected by me on **24-06-2025** with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

#### **ANNEXURE-1**

(Up to 14.99 mtrs. in height) Group B Education Building

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings sub division B1& B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory)

#### A. Details of the building / premises :-

01	Name and Address of the	:	President		
	Applicant.		Bharatiya Education Society (Trust)		
			Gadag.		
02	Name and Address of the	:	Bipin Chikkatti School		
	premises.		Near Adavisomapur, Mundaragi Road, Gadag.		
			Tq & Dt: Gadag.		
03	Name and address of the	:	President		
	Building owner		Bharatiya Education Society (Trust)		
			Gadag.		
04	Number of buildings	:	01 Building		
05	Number of floors	:	Ground Floor + Two Upper Floor		
06	Floor-wise details of occupancy:-				
	Ground Floor :		04 Class Room.		
	First Floor:		04 Class Room, 01 Staff Room.		
	Second Floor		04 Class Room.		
07	Height of the building	13	11.75 mtrs		

08	Site area	:	4046.72 Sqmtr	
09	Built-up area of each floor:-			
	Ground Floor	:	448.96 Sqmt	
	First Floor	:	448.96 Sqmt	
	Second Floor	:	448.96 Sqmt	
10.	Total built-up area	:	1346.88 Sqmt	
11.	Surrounding properties:-			
	North (Front)	:	Play Ground	
	South (Rear)	:	Agricultural Land	
	East (Side)	:	Old School Building	
	West (Side)	:	Approach Road	
12.	Set-back area available around the building:-			
	North (Front)	:	More than 03.00 mtrs	
	South (Rear)	:	More than 03.00 mtrs	
	East (Side)	:	No Space	
	West (Side)	:	No Space	
	Allowed setbacks (open space) should be maintained free from further obstruction /			
			construction	

Note: Recommended to provide and maintain setbacks as per Local ZR.

# <u>B.</u> On inspection of this School Premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view:

Sl. No. (1)	Details (02)	Existi (03)	O	Recommendations (04)
01.	Accessibility to the premises	The premise is 12.00 mtrs. V surfaced road Western	Vide hard located on	Adequate
02.	No. of entrances	01 no's of Ent Only	•	Minimum 01 Entrance & 01 Exit Should be Provided.
03.	Width of Entry/Exit	05.00 r	ntrs	Minimum 06.00 mtrs. Width with height clearance of minimum 05.00 mtrs. From Ground Level
04.	Diesel generators.	25 KVA P	rovided	Adequate
05.	No. of staircases available	Nos. of staircases :	01 no'	Recommendation to provided staircases maintain travel distance
		staircases :	2.50 Mtrs	with 22.50 mtrs. With minimum 02.00 mtrs width, 30 mm treads
	T. L.	Width of treads:	30 cm	width, 15 mm treads height, 1 mtr Handrail with minimum 02.20

\* Sale

.,		Height of risers	15 cm	head room clearance.
		Nos. of riser per flight	14 no's	
		Height of	90 cm	
		Head room	3.10	
		clearance	mtr	
06.	Public address	Not Provided   mtr		A. One CO2 type fire extinguisher, of 4.5 kgs capacity should be provided near each electrical panel board & electrical room.  B. One mechanical foam extinguisher of 9 ltrs capacity & One ABC type extinguisher of 6 kgs capacity should be provided near Diesel generator.  C.One DCP extinguisher of 4 kgs capacity should be provided in the Kitchen if provided for the purpose of Mid-Day Meal.  D. One ABC type fire extinguisher of 06 kgs capacity should be available within 15 mtrs. Radius  E.All the extinguisher suggested above should be with BIS markings and should be located at an easily accessible postion without obstructing the normal passage and maintained periodically
07.	Public address system	Not Provided		Recommended to provide public address system with talk back facility at each floor of College building with its 'Control 'at the ground floor level at Security room.
08.	First aid Hose reel hose.	Not Pro		Hose Reel Hose near the each staircase (One hose reel hose system for every 1000 sq. mtrs) The hose reel hose of min 19 mm size and of 30.00 mtrs length shall be

			having a nozzle of 5mm size. The hose reel hose should be connected at each landing of each building/block wing tower.
09.	Automatic sprinkler system.	Not Provided	Not required as there is no basement
10.	Terrace tank over respective tower terrace.	Not Provided	Terrace tank required 10,000 ltrs. Capacity for hose reel drum comer. (the water tank should be kept exclusively fire fight purpose)
11.	Pump at the terrace tank level with minimum pressure of 3.5 kg/cm <sup>2</sup>	Not Provided	Recommended to provide booster pump of 450 lpm capacity for each Hose reel drum system. Further the system should be connected to an alternative source of power supply.
12.	Fire Control Room at Ground Floor	Not Provided	Recommended to Provide fire control room at the entrance/security room.
13.	Escape routes	Not Provided	Recommended to Provide Direction in which the inmates should have to move in the event of any emergency have to be indicated in the corridor passage as a guide during evacuation staff. These marking should be in luminous paint.
14.	Fire order (Fire Safety Plan)	Not Provided	A notice board has been displayed the Action to be taken by the Students/Staffs in Case of an Emergency with Telephone Numbers of Gadag Fire Station i.e. 08372-237444, 112 & 101 and telephone numbers of nearest Ambulance Service & Management Has been displayed.
15.	No smoking board	Not Provided	As per Sec-4 of COPTA a board with words NO SMOKING AREA shall be written in English & Kannada both languages shall be prominently displayed at inside the entry/exit of the each floor.
16.	Fire Siren	Not Provided	A Fire Siren shall be installed in the premises to inform the inmates

			in case of a fire emergency and		
100			evacuate the area.		
17.	7. Water Storage 3000 ltrs UGT I		The system should be connected to		
	Capacity		an overhead tank of 5,000 ltrs.		
	Capacity		Capacity and further if basement is		
		N.	provided the tank capacity shall be		
		***	increased to 10,000 ltrs. capacity.		
		95	(The water tank should be kept		
			exclusively fire fight purpose)		
			Note: If the existing building is not		
		_	capable of sustaining the weight of		
			5,000/10,000 ltrs tank capacity		
			provision shall be made to provide water tank on the side of building		
			with support from ground level by		
			providing RCC column structure or		
			MS column structure. If there is no		
			option to provide even the above		
			mentioned overhead tank provision		
			shall be made to provide		
			underground water tank of capacity		
			with submersible pump of 5-7 HP		
			capacity.		
18.	Nominate one	Not Nominated	A Fire Nodal officer shall be		
	Fire Nodal	A THE STATE OF THE	nominated either from teaching r		
	Officer		non teaching staff		
19.	Training in Fire	Not Provided	At-least 40% of teaching or non		
	fighting		teaching Should be got trained in		
			basic fire fighting at R.A.Mundkur		
			fire & Emergency Services		
			Academy, Bannerughatta road,		
			Bangalore or Regional training		
			centre within 3 months or at ar		
			early date. And shall be submitted		
			to this office.		
20.		ecautionary measures:-			
	A. Explosi	ve and flammable materials shoul	d not be stored in the store room, UPS		
			laboratory & electrical sum panel		
	premises.  B. Accumulation of combustible waste in and around the premises should be				
avoided.  C. The exit ways shall be always kept clear without any obstruction.					
	D. Liquefi	ed petroleum og should not be et	ored in the building		
<ul> <li>D. Liquefied petroleum gas should not be stored in the building.</li> <li>E. The doors shall not be kept locked/batched during working hours and shall be from obstruction.</li> </ul>					
	outside	10/28 10/			
		3/470 * DAC	Kar		

G. As per Hon'ble Supreme Court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14<sup>th</sup> of every year by conducting Fire Safety drills with coordinate with fire service department.

Under the above circumstance the Karnataka Fire And Emergency Service Department is issuing <u>Fire Safety Recommendation</u> to Bharatiya Education Society ® Gadag Bipin Chikkatti School, Near Adavisomapur, Mundaragi Road, Gadag. Tq & Dt: Gadag.Subject to condition and compliance of the above recommendations in column 4 of serial B within 03 months compliance to the undersigned.

\*All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.4 of Fire and Life safety will have to be complied with mandatorily.

From the above details it is clear that the 'Management' of the above Educational building have been recommended to provide fire precautionary measures as per National Building Code 2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. After full-filling the above recommendations, a Certificate should be obtained by this office. If at any time any of the conditions are found not complied with, this Certificate shall stand withdrawn/cancelled.

The <u>Fire Safety Recommendation</u> is valid for a period of one year from the date of issue and it is not renewable.

To,

President
Bharatiya Education Society (Trust)

Gadag.

Copy to:

1) Office Records, DFO's Office, Gadag.

Hayanan 25/06/2025

Timataka State Fire & Emergency Services
GADAG.